

## Revision history

---

### **Software version 3.8.0**

- Release date 13.01.2021
- Fixed issue with License message at startup
- Report engine changed to newer version (Crystal report)
- Fixed issue with first start when login windows is covering the site selection window.

### **Software version 3.7.2**

- Release date 25.02.2020
- New firmware for battery operated locks version 1.75 with:
  - Increased card proximity threshold to avoid false card detections (AL-500 and ALP-500 models only)
  - Fixed bug – valid access two seconds before auto-open operation set lock in locked state until automatic restore to normal state is executed
- New firmware for 12 V readers version 1.67 with:
  - Fixed bug – valid access two seconds before auto-open operation set lock in locked state until automatic restore to normal state is executed
- Added Czech language (interface and help)

### **Software version 3.7.0**

- Release date 23.12.2019
- Fixed bug with saving validity time in Users configuration
- Added in reports option to show/hide deleted users
- Changes in Desktop reader driver
- Added Czech language

### **Software version 3.6.1**

- Release date 22.10.2019
- Fixed bug with database restore

### **Software version 3.6.0**

- Release date 18.10.2019
- Fixed bug with adding credit to card
- Added firmware 1.73 for locks with changed calibration procedure and fix for auto open action

### **Software version 3.5.1**

- Release date 26.07.2019
- Added checking for newer version
- Updated languages translations

### **Software version 3.4.2**

- *Release date 08.07.2019*
- *Added new Firmware for battery operated locks version 1.70 with fixed battery reading from software*

#### **Software version 3.4.1**

- *Release date 28.05.2019*
- *Added Firmware for readers 1.66. Removed reader pause of 3 seconds after valid access.*
- *Added battery reading for door lock with push button via USB.*

#### **Software version 3.4.0**

- *Release date 21.05.2019*
- *Added Company name and web in About box*
- *Fixed bug with saving the database to repository – Database that is not currently open will not be saved to repository, but instead database of the currently open site will be saved.*

#### **Software version 3.3.1**

- *Release date 10.05.2019*
- *Added holiday for Automatic openings (Readers and locks must be upgraded with latest firmware)*
- *Added firmware version 1.65 for locks and readers*
- *Added support for AL-500 privacy push button*
- *Fixed bug – Weekday was not configured correctly when lock was programmed with card and option for clock specific time*

#### **Software version 3.3.0**

- *Release date 28.03.2019*
- *Added holiday for Automatic openings*
- *Added support for AL-500 privacy push button*
- *Crystal report engine upgraded to 13.0.24*

#### **Software version 3.2.0**

- *Release date 28.03.2019*

#### **Software version 3.1.6**

- *Release date 18.01.2019*
- *Fixed minor graphic issues*
- *Added Holland holidays template*
- *In the locks configuration, Holiday item is moved in the Workdays check list*

#### **Software version 3.1.4**

- *Release date 25.12.2018*
- *Changed Dutch translation*

- *Fixed some not translated elements in GUI*
- *Fixed bug in blacklist form – list card types in other languages (apply to new installations)*

### **Software version 3.1.1**

- *Release date 22.10.2018*
- *Added shared backup repository*
- *Added new firmware for 12V powered readers with more automatic openings functions (firmware version 1.62)*
- *Removed checking if site database is created with current main database making possible to share site database on different installations*

### **Software version 3.0.12**

- *Release date 01.06.2018*
- *Minor changes in Lock settings form*
- *Minor changes in Users management form*
- *Description changes in changing site passwords procedure*

### **Software version 3.0.10**

- *Release date 12.04.2018*
- *Database version upgraded to v.5*
- *New firmware release ver.1.56*
- *Fixed bug - automatic opening(action parameter specifically) should work properly when changing different languages*
  - *NOTE: Automatic opening configuration will be reset (only the action parameter) to default = nothing and will have to be reconfigured, other parameters like time and days will be intact*
- *Holidays are separated from 'Sunday' in Access levels*
  - *If checked, the card will have 'access granted' for holidays. Holidays are configured in Manage/Holidays*
    - \* *The firmware must be upgraded to 1.56 for holidays to work*

### **Software version 3.0.8**

- *Release date 27.02.2018*
- *Database version upgraded to 4*
  - ♦ *New, improved icons designed specifically for PROA MS and other small design changes*
  - ♦ *Some windows were calibrated to fit smaller resolutions*
  - ♦ *New feature: option to choose Token type (Card, keychain, key fob, wristband, sticker etc) and it's color for each User in the Users management*
    - ♦ *Token types can be managed (add, remove) in Main menu/Manage/Tokens*
    - ♦ *Database upgrade will create 3 default Tokens (Card, Key fob and Wristband) and each existing user will have "White card" as default token*

Minor fixes:

- Users form:
  - search field by name won't be disabled after adding new user
  - search field by ID will allow only numeric values

### **Software version 3.0.7**

- *Release date 04.12.2017*
- *Database version upgraded to 3*
- *New firmware release ver.1.51*
  - ♦ Clock, Configuration ("Config") and Initialization ("Init") cards can be programmed with specific time and date in addition to "add minutes" option.
  - ♦ Manual is translated and integrated in the software in 5 other languages (French, Spanish, Dutch, German, Italian).
  - ♦ Added option "Time alarm" in reader configuration: when checked, the reader will flash red light every 10 seconds if the clock (on the reader) is incorrect (e.g. due to power loss); Previously this was ON by default without the option to turn it OFF (requires reader firmware update 1.51).
  - ♦ Fixed a bug - collecting the events with 4K card may block the reader and power reset of the reader was required (requires reader firmware update 1.51).
  - ♦ Maximum number of events for card with capacity of 4kB will be 127 instead of previous 204 and 40 events for card with capacity of 1kB (requires reader firmware update 1.51).
  - ♦ Fixed bug – card sectors other than 1 was not implemented properly (requires reader firmware update 1.51).
  - ♦ "Enable reader" has been removed from "Doors" configuration and it's no longer requirement in order to configure reader parameters.
  - ♦ Various small improvements and bug fixes.
  - ♦ "Event collect card" window will show number of collected events and last collected event.
  - ♦ Users can be searched by card ID

### **Software version 3.0.6**

- *Release date 03.10.2017*
  - ♦ Fixed a bug where weekdays from access levels were not displayed correctly when reading card data
  - ♦ When the "USB desktop reader" is unplugged, the "read card" button on the main menu will be disabled
  - ♦ Fixed a bug where taking snapshot from web camera wasn't working properly in Users form

### **Software version 3.0.5**

- *Release date 22.09.2017*
  - ♦ Event type name in the "event log" report will be displayed in non-technical terms (e.g. "ACK\_OK" will be "Access granted" etc)
  - ♦ Added new filters for user and door in "Event log" report

- ♦ Fixed a bug for “Error in translation..” after login

#### **Software version 3.0.4**

- *Release date 14.09.2017*
  - ♦ Fixed errors or missing translation for some controls
  - ♦ UI improvements for languages other than English where text was not fully visible

#### **Software version 3.0.3**

- *Release date 13.09.2017*
  - ♦ New firmware version for MTPX – ver.1.48
  - ♦ New firmware version for DIN – ver.1.46
  - ♦ UI improvements for languages other than English where text was not fully visible
  - ♦ Installation for different companies than XPR will be installed in the their respective folder instead of XPR folder

#### **Software version 3.0.2 (Release)**

- *Release date 22.08.2017 (Release)*
  - ♦ Added toggle option for the User card
  - ♦ Toggle and privacy override will be disabled by default when adding new User
  - ♦ Added toggle and privacy info when you “read card” for user card
  - ♦ Added automatic opening info when you “read card” for configuration card
  - ♦ Fixed a bug where you can issue replacement card on non existing user
  - ♦ When trying to issue or read card without a desktop reader connected it will give you message
  - ♦ No door/user will be selected as default when opening these forms for the first time
  - ♦ Fixed a bug where the title and filter in the reports were not showing correctly
  - ♦ Small design changes in the reports

#### **Software version 3.0.1 (Release)**

- *Release date 08.08.2017 (Release)*
  - ♦ *Database version upgraded to 2*
  - ♦ *New reader firmware release ver.1.45*
  - ♦ Backup and restore database feature
  - ♦ Automatic database upgrade
  - ♦ Configuration card and USB configuration command added
  - ♦ Reader will give “access denied” signal (red light + beep) when blacklisted, blank, factory default or any other card which was not previously used in the software is presented on the reader
  - ♦ Some main menu icons have been re-arranged
  - ♦ Changes to blacklist card form design
  - ♦ Changes to read card design